



www.continentalsports.co.uk

“TREVIRA” FABRIC WALL CLADDING



OPERATION

This fabric cladding requires no “operation” – it is designed to cover the internal face of building cladding and cladding rails to make the internal wall more attractive, to prevent dust build up on cladding rails and to stop light projectiles such as badminton shuttles landing on cladding rails.

MAINTENANCE

There are no user-serviceable elements of the Trevira fabric wall cladding. Should it sustain any damage, please contact Continental to determine how this can be resolved – the material cannot be sewn on site and may require removal and reinstallation or replacement.

The material can be wiped with a damp cloth using warm soapy water should any small stains be incurred.

Tide marks caused by water ingress or over-wetting may not be possible to remove depending on the nature of the stain.